

Technical Bulletin

Model
All

Group
9



Subject: Routing and Securing of Electrical Harnesses

Part Identifier
9709

Number
8906

ATTENTION: Service Manager/Service Technician

When working on a vehicle, it is often necessary to move and/or disconnect a wiring harness to facilitate repairs. When reinstalling such a harness, it is absolutely necessary to properly route and fasten it. The routing and installation of wiring harnesses in Porsche vehicles is carefully designed to prevent any contact with other parts of the vehicle that have the potential to damage the harness; therefore, the reinstallation must duplicate the original installation. All wire ties and harness clips should be attached in their original location. All electrical plugs and connectors should be checked to ensure proper engagement. Any insulation pads, bushings, grommets, shields and/or covers removed during repairs must be reinstalled in their original location and in a manner that will not damage the harness or related components.



Failure to properly route and secure a wiring harness after repair can result in unwanted squeaks, rattles or damage to the harness and other parts of the vehicle electrical system. Damage to the harness, if undetected, may result in short circuits and under some circumstances may result in an electrical fire.

Thank you.

PCNA Service Department

Important Notice

PCNA Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

©1989 Porsche Cars North America, Inc.

Dealership _____ Service manager _____ Shop foreman _____ Service technician _____
 Distribution _____ Asst. manager _____ Warranty admin. _____ Service technician _____
 Routing _____

©1989 Porsche Cars North America, Inc. All Rights Reserved Porsche Service Publications



SERVICE

Page 1 of 1
December 15, 1989

PORSCHE CARS NORTH AMERICA - INC.